

A close-up photograph of a tire tread. The tread pattern consists of several parallel grooves. The grooves are filled with a dark, sticky substance, which is rubber deposits. The surrounding rubber surface of the tread is also covered in a thin layer of this dark material. The overall appearance is that of a heavily worn and contaminated tire.

Rubber deposits on standard grooves

Rubber deposits on Trapezoid grooves - almost clean